

- Site Report -

Date: September 26, 2012 IRD Sales Order: 11167

To: Dawn Patton From: Bryan Knight

Project Name/Location: Kingman (US-93) LTPP, AZ

Service Date(s): June 30, 2010

Job Description: Site Maintenance

Work Completed:

• Performed visual Inspection of roadway sensors OK.

• Recorded Electrical measurements of road sensors and Solar Panel power supply OK.

• Connected to WCU and monitored system function OK.

• Performed general housekeeping of equipment cabinet and cleaned cabinet filter.

6/19/96 IRD FORM No.: 1304A







INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>





Work Remaining:

Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used:

Pre-mature Equipment Failure:

Mileage / Travel Time: Total Travel 1 hrs Total Onsite: 1 hrs

Safety Concerns:

Issues Related to Sub-Contractors:



Other Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		